



**FIG.1**




(1) State before failure




(2) State after failure of 30A


**FIG.2**




**FIG.3**



**FIG.4**



**FIG.5**



**FIG.6**




FIG.7






FIG.8






**FIG.9**  
(PRIOR ART)




**FIG.10**  
 (PRIOR ART)




**FIG.11**


(PRIOR ART)




**FIG.12** (PRIOR ART)




**FIG.13**




**FIG.14**



**FIG.15**




**FIG.16**





**FIG.17**



**FIG.18**

